


Ball Joint - UTV, Hisun, 400cc, 500cc, 700cc, 800cc - 70A6280 - PBC3298F1



Rating: Not Rated Yet
Price

\$21.53

[Ask a question about this product](#)

Description

Ball joint. Commonly used for (but not limited to) 400cc, 500cc, 700cc and 800cc engines, such as the Hisun 400cc, Hisun 500cc, Hisun 700cc and Hisun 800cc UTVs as well as many other clones, rebrands and similar displacement machines.

Common Hisun model names are primarily listed as variations of "Hisun 400cc UTV", "Hisun HS400UTV", "HSUN HS400 E-mark EFI", "Hisun 500cc UTV", "Hisun HS500UTV", "HSUN HS500 E-mark EFI", "Hisun 700cc UTV", "Hisun HS700UTV", "HSUN HS700 E-mark EFI", "Hisun 800cc UTV", "Hisun HS800UTV" and "HSUN HS800 E-mark EFI". Common listed Hisun ball joint previous part number is 63140-055-0000 and current part number is 62610-115-0000, listed as "Ball Joint,Steering Machine" in their parts lists. Also applies to some variations of Hisun ATV models.

Common Nordik model names are primarily listed as "Nordik Blizzard NK400U", Nordik Blizzard NK500U", "Nordik Blizzard NK700U" and "Nordik Avalanche NK800U". Common listed Nordik NK400U, NK500U, NK700U and NK800U ball joint part number is P115N00642100100, listed as "Ball Joint,Steering Machine" in their parts lists. Also applies to some variations of Nordik ATV models.

Common Powermax model names are primarily listed as "Powermax Roughrider 400 UTV", "Powermax Roughrider 500 UTV", "Powermax Roughrider 700 UTV" and "Powermax Roughrider 800 UTV". Common listed Powermax ball joint previous part number is 63140-055-0000 and current part number is 62610-115-0000, listed as "Ball Joint,Steering Machine" in their parts lists. Also applies to some variations of Powermax ATV models.

Manufacturer Part Numbers:

- 63140-055-0000
- 62610-115-0000
- 62610-115-0001
- P115N00642100100